

AL-7000



Features:

- Units of measurement : meters (m) /hpa

Technical Features

	Basic Function
Measuring Range	0-5000m/580-1040 hpa
Resolution	20m /5 hpa
Operating Temperature	-20°C - +60°C
Storage Condition	-30°C - +65°C;<90% RH

- Standard Accessories : Neck Strap +Belt Hook
- Dimensions : 85 x 68 x 28 mm
- Weight : 90g

AL-7010



Features:

- Altitude history & Graphical Display of the last 12 hour altitude readings.
- Total Altitude Gain & Loss
- Max./ Min. memory for Altimeter and Barometer Pressure
- Barometer Pressure History & Graphical Display
- Electronic barometer Weather Forecast (Sunny, Slightly Cloudy, Cloudy, Small Rain, Large Rain)
- Pressure Trend Indicators
- Perpetual Calendar with day of week
- 12/24 hour selectable
- Low battery indication

Technical Features

Basic Function	Metric	Imperial	Basic Accuracy
Altimeter	500 ~ 9000 Meters	-1600 ~ 29500 feet	1 meter / foot
Barometer	300 ~ 1100 hPa/mbar	8.84 ~ 32.44inHG	1 hPa / mbar (0.01HG)
Indoor Temp.	-10 ~ 60°C	14 ~ 140°F	0.1°C (0.18°F)
Humidity	20% ~ 90% Rh		1% RH
Stop Watch	9hr 59min 59sec.		1/10th Sec. or Sec.

- Standard Accessories : Handy Belt, Manual
- Dimensions : 177(H) x 98(W) x 39(D)mm

